



ARTIC WOLF PRO BACK PACK ARTIC FOX PRO WAIST PACK

Instructions for Use

1. Charge battery before each use. A light on the charger will illuminate green when battery is fully charged. Battery is usually fully charged in 3.5 - 4.5 hours.
2. Connect power plug from bag into side of battery. Secure battery in front pouch of bag.
3. Verify inside of bladder is clean and free of debris and add items below.
 - 1.5 pounds of ice
 - 16 ounces of water
 - 2 ounces of Paragon Pro Defense solution
4. Connect the male connectors from the garment into the female connectors on the bag. A water supply hose may be added for remote mounted bags. An audible click can be heard when the connectors are properly connected.
5. Power the system on.

Preventive Care and Maintenance

1. Empty water and clean inside of bladder. Let bladder air dry.
2. For periods of longer storage, pour water into bladder and add 16oz. of Paragon Pro Defense solution.
3. Cycle water & solution mix throughout system for ten minutes.
4. Empty bladder and allow to completely air dry before putting into storage.

Popular Accessories

- 01-50000 Defense 16 ounce bottle
- 01-51000 Everlast Ice
- 53-40000 Drain kit
- 12-40000 Female Connector
- 02-29400 Artic Wolf/Fox battery
- 03-29400 Artic Wolf/Fox battery charger